









Assembling Instruction

(1) Base	(2) Gas Column	<p data-bbox="658 209 703 264">A</p> 	<p data-bbox="1395 197 1440 253">B</p> 
			
<p data-bbox="136 651 174 676">(5)</p> <ul style="list-style-type: none"> <li data-bbox="152 775 472 807">1.  x4 (6x50) mm <li data-bbox="152 847 472 879">2.  x4 (6X16) mm <li data-bbox="152 919 338 951">3.  x5 <li data-bbox="152 1007 421 1038">4.  x1 5mm 		<p data-bbox="640 911 685 967">C</p> 